

**FITNESS CERTIFICATE FOR SCHOOL BUILDING**

- 1 Name of the Officer : Thimma Kudiya .O
- 2 Name of the School : Sadguru Shri Nithyananda Vidyapeeta
- 3 Location with Name of Education : Kondevoor,Manjeshwaram,  
Dist/ Sub Dist : Kasargod
- 4 Classification of building as specified in column 4 of the application for Fitness Certificate

**Permanent**

1.6.00 x 8.00 x 3.60	4no's class room	6.30.38 x 2.00 x 3.60	1no's varandah
2.6.00 x 8.00 x 3.60	1no's office room	7.6.00 x 8.00 x 3.60	5no's class room
3.30.38 x 2.00 x 3.60	1no's varandah	8.4.05 x 11.04 x 3.60	1no's library
4.6.00 x 8.00 x 3.60	5no's class room	9.30.38 x 2.00 x 3.60	1no's varandah
5.4.05 x 11.04 x 3.60	1no's staff room	10.40.60 x 10.00 x 3.60	1 no

- 5 Period for which the certificate is issued : 2024-2025
- 6 Nature of defect : N.A
- 7 a) Foundation and basement : RCC Framed and Laterite  
b) Super Structure : RCC and Laterite  
c) Doors and Windows : Country Wood  
d) Wood work wrought and put up : Country Wood  
e) Roof : RCC & TILED  
f) Flooring : Floor Tiles
- 8 Any major defects modified which will render the building unsafe in any manner : NA
- 9 Whether maintenance works have been done properly : Yes
- 10 Whether Structure is sound or not for Conducting class: **The above mentioned buildings are Found SAFE for conducting classes in Normal wind and weather conditions.**

**Certified that the school building was inspected by me on 11/07/2024 and the above mentioned buildings only are found to be FIT to conduct class under Normal Weather condition.**

Place : Mangalpadu  
Date : 11.07.2024



Assistant Engineer *11/07/2024*  
**ASSISTANT ENGINEER**  
LSGD SECTION  
MANGALPADU